



Ceramic Coatings

C-106 Water based ceramic non-stick coating

TYPECeramic nano materialKEY• PFOA free and excellent heat resistant• Excellent and lasting non-stick performance, easy to clean• Excellent chemical resistance, corrosion resistance an abrasive resistance• AppearanceWhite liquid (Prime and top)• Solid content (%)35±1• Viscosity (cp)600~900 Primer 400~700 Top
 FEATURES Excellent and lasting non-stick performance, easy to clean Excellent chemical resistance, corrosion resistance an abrasive resistance Appearance Solid content (%)
Appearanceand top)Solid content (%) 35 ± 1 Viscosity (cn) $600 \sim 900$ Primer
Viscosity (cn) 600~900 Primer
Viscosity (cn)
Density (g/ml) 1.20 Primer/1.30 Top
pH 8-11(Primer and top)
TYPICAL Color of the film surface White (Flat and smooth)
Curing temperature (°C) 280-300
PROPERTIES Gloss (60 ° glossimeter) 10-20
Film thickness (µm) 30-45
Non-stick performanceFry eggs at 170±10℃
Corrosion resistance Boling 10% salt water for 24 hours
Abrasion resistance 3KG/21cm² >4000 cycles
Hardness (ZHONGHUA pencil) >F
APPLICATION Cookware and bakeware made of aluminum, stainless an carbon steel etc.
• Available in 20 kg/ barrel or 30 kg/ barrel
 Store products in tightly closed original containers at 5-40°C Shelf life: 9 months from delivery date
According to non-dangerous goods transport

Add.: Hefei city, Anhui province, China Mob: +86 15855525589



1. Requirement on pre-treatment

- Firstly, apply high-temperature degreasing, then wash with 1%~3% NaOH solution (60°C) for more than 6 minutes, dry it after water rinsing;
- Blast with $80\#\sim120\#$ corundum to make the surface roughness reach $2.0\mu\sim3.0\mu$, pay attention to sandblast evenly;
- Wash with 1%~3% NaOH solution(60°C) for more than 6 minutes, rinse with water;
- Wash with 1%~3% hydrochloric acid solution (60°C) for more than 6 minutes, rinse with water and dry.
- 2. Preparation of the coating
- Dispersion of coating: the coating must be fully dispersed before operation;
- Viscosity adjustment: the viscosity could be adjusted according to different spray methods. Dilute with clean water if the viscosity is over high;
- Coating filtration: filtrate the coating with screen (100mesh) before using.

3. Application

- **HOW TO USE** The spraying environment should be dry, well-ventilated, no smoking and fire. We suggest using dedicated spray gun, elevated tank and curing oven;
 - The air compressor should be degreased, dewatered and equipped with water oil separator before using;
 - Roll the coating at 30rpm speed before using to make sure there is no sediment, and filter with 100 mesh screen;
 - Adjust atomization and oil pump capacity of the spraying gun; make sure the unit is clean and flat;
 - Preheat the substrate to 35°C and spray the primer. Dry it at temperature of 120°C~150°C for 10min-15min. Keep the thickness of primer within 15µm-22µm;
 - Spray top coating after the primer is dry and cooling to room temperature, then spray the top. Dry the unit at the temperature of 100 °C ~150 °C for 10min, and gradually increase the temperature to 280 °C ~300 °C. Keep for 10 min. Keep the thickness of top coat within 12µm~20µm. The thickness of two coat tally should be between 30µm~40µm;
 - The oven (or the tunnel drier) must be well ventilated; otherwise, it will lead to color change of coating.